



STATE OF TENNESSEE
DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Solid Waste Management
Fifth Floor, L & C Tower
401 Church Street
Nashville, Tennessee 37243-1535

RETURN RECEIPT REQUESTED
7003 1680 0005 5757 8574

February 13, 2004

Jim Reed
SOUTHNAVFACENGCOM
2155 Eagle Drive
P.O. Box 190010
North Charleston, SC 29419-9010

Re: Interim Measures (IM) Report
Solid Waste Management Unit (SWMU) 3 – former N-121 Plating Shop
Naval Support Activity Mid-South, Millington, TN
Tennessee Hazardous Waste Permit Number: TNHW-094
EPA I.D. Number: TN2 17 002 2600

Dear Sir:

The Division of Solid Waste Management (Division) has reviewed the IM Report prepared by EnSafe Inc. The IM Report describes a soil removal at SWMU 3. Soils at SWMU 3 were contaminated with hexavalent chromium above relevant action levels. On October 16, 2003, approximately forty (40) cubic yards of soil was removed from SWMU 3. After contaminated soil was removed, EnSafe performed confirmatory sampling to determine if the remaining soils met the established cleanup criteria. Based on the information and sampling data provided, the Division has determined that remedial objectives were met and no further action is necessary at this time at SWMU 3.

If there are any questions or comments regarding this review, please contact Roger Donovan at (615) 532-0864 or e-mail at roger.donovan@state.tn.us.

Sincerely,

A handwritten signature of Roger Donovan, written in black ink, is located below the "Sincerely," text. The signature is stylized and appears to read "Roger Donovan".

Roger Donovan, P.G.
Corrective Action Section

cc: Jennifer Herndon, EPA, Region 4, Federal Facilities Branch
John Stedman, EnSafe
William Krispin, Manager, Permitting Section,
Charlie Burroughs, Manager, Corrective Action Section
Philip Davis, Manager, Memphis EAC
HWPU File # 56
CADOTS #2004126IM-494